



# Lessons Learned from a Bridge Abutment Failure

GeoVirginia 2015



Raymond A. DeStephen, PE  
April 29, 2015

# The Project - Bridge Overpass, Chesapeake, Virginia

---



# Project Completion

---

- Bridge designed in 1987
- Construction started Spring 1990
- Construction completed by 1992
- Remedial Evaluations 2000 to 2003
- Reconstruction 2007




# Project Details

---

- Bridge is 100 ft wide and 250 ft long
- Approach embankments: 35 ft high; 90 ft upper width; 2H:1V slopes
- Piers and abutments on 12 inch prestressed, precast concrete piles; 70 and 100 ft long, respectively



# Subsurface Conditions and Design




# Properties of Great Bridge Formation

---

- LL = 52 to 98; PI = 31 to 68; MC = 53 to 92
- Passing No. 200 sieve: 93 to 99%
- Organic content 5.4 to 17.8%
- $C_c = 0.6$  to 2.2;  $e_o = 1.4$  to 2.6
- OCR = 1.0 to 1.7
- Lab  $S_u = 500$  to 800 psf; N-values = WOR to 2



# STRESS CHANGE FROM EMBANKMENT LOADING



# Preliminary Report Conclusions

---

Support bridge on 12-inch concrete piles in Yorktown formation sands and clays for an allowable 100 ton capacity.

Note: No mention of allowance for drag load on piles.






# Preliminary Report Conclusions

---

- “Embankment settlements of 2.5 to 3.5 ft are predicted”.
- “While the time required for the total completion of primary settlement is in years, 80% is likely to occur in the first 3 months”.
- “Typically in non-homogenous clays with potential sand lenses, settlement rates in the field are usually faster than predicted”.
- “It may be possible to accelerate settlement by installing wick drains...”



# Estimated Time of Embankment Settlement



SCALE:	APPROVED BY: <b>SAB</b>	DRAWN BY: <b>JEC</b>
DATE: <b>7-10-87</b>		PROJECT: <b>NK7-1580</b>
<b>Chesapeake Roadways - Route 17 Chesapeake, Virginia</b>		
<b>Settlement v.s. Time</b>		DRAWING NUMBER: <b>5</b>



# Preliminary Report Conclusions

---

- “Consolidation testing indicates sampling procedures are disturbing the soil... recommend in situ testing”.
- “Based on prototype test berm...settlements based on dilatometer results were significantly more accurate than those predicted by classical consolidation tests...those settlements were also substantially smaller.”



# Final Geotechnical Report

---

- Pile recommendations were unchanged
- No estimate of drag load on piles given
- Settlement estimate reduced to 2.25 ft based on DMT results
- No recommendation for wick drains
- 80% settlement complete in 3 months

Note: This leaves 6 inches of predicted primary consolidation and about 3 inches of secondary compression remaining.



# Construction Assumptions

---

- Construct embankments and wait three months for the predicted 2.25' of settlement to occur
- Release embankments to the contractor for bridge construction based on performance data
- Drive abutment and pier piles



# The Astute Bridge Designer Has a Question

---

- What about drag load?
- Answer - 15 to 20 tons
- Amendment No. 1 issued by the geotechnical consultant - “drive piles an additional 10 feet to account for any drag load”



# Pile Installation

---

- Pier piles designed for 80 tons and abutment piles for 100 tons
- One static load test conducted at the piers – none at the embankments
- All bridge construction including piles were monitored **by the owner**



# Pile Installation

---

- Final pile resistances were highly variable
- Some  $>100$  blows/ft and some  $< 40$  blows/ft depending on bearing on clay or sand
- Final tip grades varied by 22 ft





# Instrumentation Program Was Impressive

---

- Ten settlement plates
- Three piezometers
- Four vertical slope indicators
- Two horizontal settlement profile indicators




# Field Data – Horizontal Indicator

## GROUP F ROADWAYS

SOUTH HORIZONTAL INDICATOR


Project Number NK9-2240



Drawing 10




# Pore Pressures in Organic Clay Layer




Pore pressure dissipation only about 30% three months after embankment completion (not 80%)




# Semi-log Plot of a Typical Laboratory Consolidation Time Curve



# Field Data - *Arithmetic Time-* Settlement Plot Of Embankment



# Semi-log Plot of Embankment Time-Settlement Data



# Conclusions from the “Report of Embankment Instrumentation”

---

- “Horizontal indicators indicate that the (vertical) settlement is still occurring”.
- “Horizontal movement continues...may still be experiencing plastic flow”.
- “While pore water pressures have reduced, values indicate consolidation is still occurring”.
- “Construction of the overpass bridge and pier foundations can proceed”.



# Early Problems

---

- Jan 1992 City noted that “approach grades were lower than bridge grades”
- Final bridge inspection May 1992 – no major deficiencies were noted
- Dec 1996 - additional 11 to 18 inches of settlement noted
- By May 2000 – Additional embankment settlements were 2.5 to 3 ft!

(Note: Total of 5 to 5.8 ft since construction began).





# 1997 and 2003 Schnabel Studies

---

- 1997 Study: Described the cause of the observed damage
- 2003 Study:
  - Installed new piezometers
  - Performed laboratory testing
  - Predicted future settlements
  - Made remedial recommendations



# 2003 Study Results

---

- Organic clay is consolidated 75 to 95% near the top of the layer and 55 to 75% in the middle.
- Strength gain of about 50% in organic clay has occurred due to consolidation
- Future consolidation settlement up to 22 inches could occur with about 12 inches in the next 17 years.



# VISUAL DAMAGE

Depressed sidewalk and guardrail



Vertical crack on  
beam web above  
bearing plate





Diagonal Stress Crack in Under Beam

# Cracked and Grouted Beam



# Rotation of Back Wall

Displacement relative  
to girder



# Buckling of Slope Protection





# Diagonal Crack in Wing Wall




# Owner Seeks Recompense

---

- Maintenance costs for filling approach slab depressions five times over 10 years totaled about \$500,000
- Bridge inspections were performed periodically since completion
- No one asked what is going on underground to cause structural damage, or if it would get worse



# A Peek Below



**Vertical and Battered Piles Exposed within  
Void Beneath Abutment Foundation**

# Concrete Spalled/ Reinforcement Exposed



Exposed Reinforcing Steel

# Tension Failure of Piles due to Negative Drag

Pile head within  
abutment foundation



Remainder of pile has settled with soil.



You mean they're.....gone?

---



# Contractor Opines on Negative Drag

---

“I’d always heard you geotechnical guys talk about negative shaft friction, but I never believed in it until now”.





Geotechnical Engineer –  
peeks under failing  
abutment but does not  
crawl in





Bridge Engineer –  
crawling out from  
under failing abutment

# Dragload

---

Calculated as 100 to 120 tons (considering strength gain in clay and drag from overlying sand and embankment fill)

This is 5 to 6 times the original estimate!



# Vertical Pile Loads

---

- Working loads 40 to 60 tons
- Combined working loads and negative drag loads exceeded the design allowable capacity of 100 tons
- For piles bearing in clay the capacities were far exceeded



# Post Construction Pile Settlement

---

- Center pier piles: up to 1.5 inches
- End pier piles: up to 3.5 inches
- Abutment piles: 4 to 12 inches

As expected, pile settlements varied with distance from the approach embankments.




# A Case for Lateral Squeeze

---

- Slope indicators showed considerable lateral movement
- Joint displacements of 4 to 6 inches between the slope protection and abutment stem plus abutment tilting
- FHWA rule of thumb criteria exceeded for lateral squeeze (embankment pressure greater than 3 x undrained strength)



# Rotation of North Abutment



# Remedial Alternatives

---

- Underpin with micropiles
- Underpin with jet grouting
- Partial reconstruction – provide new support for end spans



# Final Remedial Design

---

- Reconstruct bridge abutments
- Leave piers and bridge spans in place
- Do not reuse existing back walls and abutment piles
- Use 16" dia. steel pipe piles with 80 ton allowable capacity
- Limit future pile drag load to the extent possible






# Remedial Design and Testing

---

- Use temporary bent to support span while replacing abutment
- Minimize drag load
  - Case upper 50 ft
  - Use pile coatings within clay
- Test piles during construction
  - Dynamic testing: initial drive and restrike
  - Static testing:
    - Compression test on full length pile
    - Tension test on cased & coated portion.



# Reconstruct Abutment Using Temporary Pier to Support Bridge Deck



# Access Holes Cut Through Bridge Deck



# Jacking Up End Span



# Temporary Shoring



# Pipe Piles with Friction Reducer



# Pile Coatings Applied




# Hardened Coatings on Piles





# Control Piles being Driven



# PDA Testing



# Pile Load Test



# Contractor Insisting He's Right In a Robin Hood–Little John Type Standoff

---



# Pullout Test Setup



# Shear Failure Appears to be Mostly in Clay

---



# Lessons Learned

- Using the least conservative method to predict consolidation may not always be the best choice.
- When calculating negative drag, account for strength gain in the compressible material, and don't underestimate strength of more competent overlying layers.
- If you plot field consolidation data **arithmetically** you just might come to the wrong conclusion.
- You cannot ignore redundant field performance data no matter how bad the news is.
- If you inspect a bridge and it seems to be falling apart – you have to ask “why?”



# Lessons Learned (continued)

---

- Observation of construction by people unqualified to do so is a formula for disaster.
- Using pile coatings to reduce pile friction may be dubious, particularly when you're trying to coat a cylinder.
- Don't argue with a contractor while standing above ground on a narrow beam.
- Don't crawl under failing structures (unless you're a bridge engineer).





# Questions??

---

