

Dams and Reservoirs; Lessons Learned

Ray E. Martin, Ph.D., P.E., D.GE



Outline of Case Histories

- Excavations in Reservoirs - **a really bad idea**
- Differing Foundation Stiffness – **expect differential settlement**
- Internal Erosion - **the number 2 cause of dam failures**
- Karst – **always a concern**

Karl Terzaghi



"---the principal function of theory consists in teaching us what and how to observe in the field."

"I consider Engineering Geology an essential antidote against a too theoretical approach to practical problems."

Professor Dick Goodman on Terzaghi in The Engineer as Artist

"---he tried to see the whole of the problem, beginning with geology, and ending with measuring behavior during and after construction."

Excavation in Reservoir

Ted Turner Fishing
Dam/Reservoir,
Flying D Ranch
(15 mi²),
Gallatin Gateway, MT
(1996)



Montana Dam Design

- 40 ft high homogeneous dam - sandy clay and clayey sand
- Surface of reservoir – 6 to 10 ft of clay over sand/gravel
- Borrow pit about 1 mile from reservoir site
- Technician sent home with 7ft of fill needed to reach crest
 - Budget for observation and testing expended
- Contractor then excavated remaining fill from reservoir


After Reservoir Filled – Urgent Call

- Ranch manager called: “seepage flowing from toe of dam on right side of outfall pipe”
- Ray: “Drain the lake ASAP”
- What caused the seepage?



Repair

- Backfill excavation with compacted fill from borrow pit
- Construct inverted filter-drainage blanked over seepage area




Excavation in Reservoir

Soledad Gold Mine
Tailings
Dam/Reservoir,
Honduras (2007)



Tailings Disposal Facility Dam Design

- Downstream construction of a tailings dam – 43m high
- Appeared well designed–borings/seepage/stability analysis



Reservoir Design


- Reservoir underlain by lean clay residual soil/limestone rock
- Test pits and geologic mapping in reservoir
- No reservoir seepage analysis - impermeable liner
- Pond 1.5mm-thick LLDPE liner underlain by geogrid
- Designed to span sinkhole 20ft in diameter 5ft deep
- Decant structure limited pond water volume to 50,000m³
- Two borrow areas for dam construction within reservoir
- Do you see a potential problem?

Construction


- Several sinkholes opened in reservoir during construction
 - Some borrow material had been removed over limestone
 - Occurred during wet weather periods
- Geogrid and geosynthetic liner placed over
 - Residual soil
 - Exposed rock – unrelated to borrow excavations

Adverse Geologic Conditions

- Borrow area expanded to include failure area



Failure



Failure

- Liner seams likely failed - differential movement?
- Seepage entered soils reduced in thickness by excavation
- Soil piped into limestone solution features
- Sinkhole formed
- Liner/geogrid failed to support water load over sinkhole
- Pond drained into subsurface and exited downstream
- A large environmental problem in stream

Excavation in Reservoir

Marlin Gold Mine Tailings
Dam/Reservoir – San
Miguel, Guatemala (2006)



Gold Mine Tailings Dam Design

- Height – 80 m
- Constructed in three stages – centerline construction
- Rock fill dam with clay core and cutoff trench
- Grout curtain
- Internal filter drainage system (chimney drain)
- Dam appears to be well designed
- Reservoir was unlined

Covering Tailings with Geosynthetic/1.5m Soil



Tailings Reservoir

- Shallow residual soil cover over rock
- Rock is highly fractured tuff and metamorphic rock
- Groundwater reported 200m below surface
- Statement from design review document:
 “Suitable dam core material occurs in relatively small pockets scattered within the reservoir.”
- Tailings contain heavy metals
- What problem could occur given the geologic setting?

Differing Foundation Stiffness

Upper Tamakoshi
Hydropower Dam,
Lamabargar, Nepal
(2015)



Overall Project Characteristics

- Peaking, “run of the river” facility
- Construction began in 2012, stopped by 2015 earthquakes
- Estimated cost = US \$441 Million
- Components impacted by earthquake
 - 22 m high concrete gravity dam (abutments, intake, spillway)
 - Two 225 m long desanding basins
- Little or no damage
 - 8.4 km long power tunnel, penstock with 822 m head drop, 456 MW in-mountain powerhouse, tailrace tunnel

Location Map



Panel of Experts (POE) Called to Evaluate Headworks Area - Displacements

- Binod Tiwari, Ph.D., P.E., Cal. State Fullerton
- James K. Mitchell, Sc.D., P.E., D.GE, Chairman
- Izzat M. 'Ed' Idriss, PhD, P.E.
- William F. Marcuson, III, PhD, P.E.
- Ray E. Martin, Ph.D., P.E., D.GE



Earthquake History/Landslides

- Historically, 10 earthquakes $>M7.0$ since 1255
- Two major recent events:
 - $M_w = 7.8$ on April 25, 2015
 - $M_w = 7.3$ on May 12, 2015
- More large earthquakes will occur
- Several landslides occurred in valley during recent earthquakes
- Potential for future major landslides was not investigated in design of headworks facilities

Local Geology

- Gneiss rock at dam site abutments - strongly foliated/ highly fractured
- Deep river alluvium exists under dam
- Deposited behind ancient landslide dam
- Landslide dam – 2.5km downstream of new dam
 - Estimated age – 2000 years
 - Most landslide dams are not stable – usually eroded by river
 - Perhaps stable because large boulders armor downstream surface





Landslide Dam

- 39 M m³ in landslide dam
- 18 M m³ of alluvium behind landslide dam
- 300 m high

Dam Foundation

Profile Along Segment of River where Dam is Located

Average Slope of Segment Shown = $(2300-1300)/14480 = 6.9\%$
 Average Slope of Landslide Dam Downstream Face = $(2000-1650)/1280 = 27\%$



- Illustrates estimated depth of alluvium under center of dam

Summary of Foundation Conditions

- Right abutment - monolith anchored to rock
- Intake and spillway monoliths
 - 8 m of alluvium removed
 - Replaced with 5 m of compacted fill
 - Shallow cutoff wall
 - ~120 m of alluvium below fill
 - Maximum investigation depth = 46 m
- Left Abutment – planned to be anchored to rock - actually a very large boulder



Right/Left Abutments



Spillway

Cross Section

Spillway and Inlet Monoliths supported on compacted fill from about EI 1964 to 1959

EI 1970

EI 1964


Sheet Piles

Jet Grouting

EI 1960

EI 1950


Grouted zone






Foundation Questions

- What impact would you expect earthquakes to have on dam?
- Did previous earthquakes densify alluvium?
- Will future earthquakes continue to densify alluvium?

Headworks Movements



Post Site Visit Borings – Rock 121 m (2016)



Cause of Settlement/Displacement

- Liquefaction
 - Volumetric strain $\sim 1\%$ - limited depth of liquefiable soil
- Volumetric compression (densification)
 - Volumetric strain $\sim 0.15\%$
- Tectonic movements
 - Possible strike-slip movement on fault in valley
 - Evidence not supportive
- Panel conclusion - densification was likely cause
- How would you have designed the dam?

Internal Erosion - General Comments

Piping is the number 2 cause of dam failures worldwide


Internal Erosion/Piping

- Piping - backward erosion of soils from an unfiltered exit under a sufficiently high exit gradient to cause soil particles to erode and form a “pipe” to the upstream source of seepage
- Silts and sands most susceptible
- Gravel and larger size particles are susceptible if gradients are sufficiently high

Critical Gradient/Roofing

- Gradient which initiates soil particle movement
- Upward vertical critical gradient, $i_{cr} = \gamma'_m / \gamma_w$
 - Often assumed to be 1
 - Depends on the unit weight of the soil – for example
 $\gamma = 112.4 \text{ pcf}$ is: $i_{cr} = \gamma'_m / \gamma_w = (112.4 - 62.4) / 62.4 = 0.8$
- i_{cr} can be lower when flow is sloping down – 0.6 to 0.3
- Piping enabled by material that provides “roof” over pipe

Surface of Seepage/ Internal Erosion/A Failure




Internal Erosion

Teton Dam, Fremont &
Madison Cos. Idaho





Teton Dam Piping Failure – 1976 -14 Deaths



Cross Section Looking Down Stream

- Fractured rock excavated in upper portion of Core Trench
- How erodible is silt?



Internal Erosion

Golf Course Dam,
Williamsburg, VA (1980's)



Williamsburg Golf Course Dam

- Small dams can fail by piping
- Homogeneous 15ft high embankment dam constructed of sandy clay/clayey sand
- Cradle in lower 10 percent of pipe
- Reservoir filled – 10ft of head
- Failed over night along pipe

Failure

- How did it fail?




Internal Erosion

Swift No. 2 Dam, Lewis River, Skamania County,
Washington (2005)

Swift No. 2 Hydropower Project

- Constructed - 1957 – 1958
- Length of water supply canal – 3 miles
- Impoundment - 2400 ac-ft
- Embankment height in forebay – 93 ft



Foundation Stratigraphy

- Stratum A - alluvium/colluvium – sand and gravel (10 to 20 ft thick) – Recent
- Stratum B – vesicular to massive highly jointed basalt rock (8 to 50 ft thick) – from Mt. St Helens (about 2000 years old) - Recent
- Stratum C – alluvium - silt, sand, gravel, cobbles, boulders (> 200 ft thick) - Pleistocene
 - Stratum C1 - silt and sand
 - Stratum C2 - gravel, cobbles, boulders (< 5 percent silt/sand)

Post-Construction Canal Leakage

- 1958 - Seepage loss from canal ~ 100 cfs (45,000 gpm)
- 1959 - Canal drained twice, numerous sinkholes repaired
- 1974 - Boils at downstream toe of the forebay embankment
 - *"An inspection of the river bank---several places where water was cascading into Yale Reservoir---appeared to be clear."*
 - Canal drained; numerous sinkholes repaired
- 2000 - Seepage observed along Lewis River/Yale Reservoir
 - *"The flow appeared to be clear, but has been reported to be turbid during periods of high runoff.---seepage gradient should be small" [FERC Report]*

April 21, 2002 Failure

- Blowout occurred at toe of embankment at about 3:00 AM
- Orifice expanded upstream causing breach of the embankment at about 5:20 AM
- Flooding destroyed downstream facilities
- Sinkholes discovered in forebay
- Discharge contained in downstream reservoir


Failure in Progress






Post Construction View/Post Failure View



Piping Failure



Piping and Blowout Unfiltered Exit



- Why did it take 44 years to fail?

Internal Erosion

Tailings Reservoir Rim
Failure, Sand Mine, Camden,
TN (2014)



Tailings Pond Rim Piping Failure



Failure on October 26, 2014

- A 911 call at 9:51PM from home north of CSX track – “flooding”
- A CSX Railroad train derailed at about 10PM
- The Pond contained about 79.6 million gallons of water at failure
- In use for about one year

Breach

Geology

- A - Fill – for access road
- B – Clayey sand
- C - Upper McNairy fine sand
- D - Lower McNairy cemented sand/silt/clay
- Note head cut blocky area in cemented soil
- Water depth at rim – 25.7 ft



Ground Surface Left of Breach

- Ground Surface 3.5 ft higher than at breach
- Head – 22.2 ft or 3.5 ft less than at breach
- Pushed stick in ground 3 ft at location of flow
- How did failure occur?



Dam/Reservoir in Karst

Zongolica
Hydropower
Dam/Reservoir,
Veracruz State,
Mexico (2015)




Project Location



Project Site

Understand the Site Geology

- 2008 Geotechnical Report, Section 4.5 – Local Geology
“ [The formation includes]---limestones and some dolomite horizons --- of the Orizaba formation---.”
- What geologic features can be observed?



2008 Field Investigation/Geology

- Reservoir - limestone
 - No investigation or borings until after dam was constructed
- Dam (30 m high) - limestone
 - 2 borings - little solutioning indicated on logs
 - Water pressure test data: $k = 10^{-4} - 10^{-5}$ cm/sec
- What does this range of k-values indicate?
- Power tunnel (2.7km long) - limestone
 - 1 boring - little solutioning indicated on log, no pressure tests
- Powerhouse – sandstone and shale
 - 6 borings
- Why?

2012 Geotechnical Report Prior to First Filling of Reservoir


- Gray limestone, contains minor interbedded red shale
 - Rock is of very good quality
 - Concave rock structures generated by dissolution
 - Discontinuous small cavities observed along fractures
- “Neither karstic sinkholes nor visible infiltration that could affect the water reservoir were observed.”



First Filling of the Reservoir

- Problem – *“the reservoir is leaking so much we can’t operate in dry season”* - reservoir could not be **filled** at 1.5 m³/sec stream flow
 - Flow ranged from 0.5 m³/sec in dry season to >4.5 m³/sec in wet season
- We needed a local geologist!

Carlos Garcia, Geologist - Comments




- 75% of wells installed found groundwater below stream



- It is likely that groundwater is well below river
- River is perched
- Landslide in reservoir is a remnant of an ancient sinkhole

Upstream Ancient Sinkhole from Ridge Line



Vertical Shaft in Limestone Quarry in Upstream Ancient Sinkhole



Remedial Alternatives – 8 Months to Finish

- Grouting Reservoir - **risks with grouting too high**
 - Upside cost of grouting unknown – how deep – 200m
 - Need to create a bathtub – not likely possible
 - Maximum available for remedial repair - \$10 million
- Lining Reservoir
 - Line portions of reservoir side walls with shotcrete
 - Based on geologic mapping
 - Line bottom with concrete slab
- What is the potential problem with lining reservoir?

Fiberglass Rock Bolts with WWF/Rebar and Shotcrete on Sidewalls and Concrete Slab




Landslide Looking Upstream from Spillway



- Temporary Solution - design and construct a soil nailed slab over base of landslide to operating level of reservoir

Slope Protection Issues

- What concerns would you have with this soil nailed slope protection?
- 1 - Shallow above soil nailed slope protection
- 2 - Deep seated downslope from roadway
- 3 - Deep seated under roadway




Summary

- Estimated cost of project – about \$100M
- Actual cost pre-repairs – about \$80M
- Remedial repairs to reservoir - \$10M
- Remedial repairs in the tunnel and penstock thrust blocks - \$10M
- Cost after remedial repairs – about \$100M
- The reservoir holds water
- The slope has not failed, yet (2016)


Dam/Reservoir in Karst

Clifford Craig Dam/Reservoir,
Roanoke Co, VA (1986-1996)




Geomorphology

- Dry Hollow, large sinkholes, disappearing stream
- Spring Hollow, steep slopes, caves & springs
- Cove Hollow, dry tributary valley




Geologic Setting

- Rome Formation shale interbedded with **limestone and dolomite layers**
- Successive large tight folds
 - Top half of folds had been eroded in past geologic history
 - Bedding dips steeply to north towards Roanoke River
 - Formation strike is east-west perpendicular to valleys
 - Major fractures oriented north-south, perpendicular to strike



Structural Geology


- Creeks aligned along major fracture orientation
- Section A-A - Dry Hollow 130 feet higher than Spring Hollow and Cove Hollow



Dry Hollow/Spring Hollow



Broad valley




Steep sided valley

Hydraulic Connection

Legend



- SH** - Sinkholes
- X** - Disappearing stream
- C** - Cave
- S** - Springs

- What occurred at this site in past geologic history?



Drilling Program

- Borings drilled along ridge lines on both sides above Spring Hollow
- Voids and caverns located along both sides of Spring Hollow at valley level
- Geomorphology sequence confirmed






Possible Solutions


- Abandon site – too risky, reservoir may never fill
- Design a reservoir grouting program
 - Numerically model seepage conditions – pre-and post grout
- Evaluate risk - develop a test grouting program
 - Monitor spring flow, estimate production grouting cost
- Results of test grouting program
 - Spring flows not modified significantly – test section too short
 - Grout takes indicated production grouting costs acceptable if test section representative of remainder of grouting area

Pre and Post Reservoir Groundwater Contours

- Seepage loss no grouting – 4MGD
- With grouting - reservoir leakage evaluated assuming fractured rock conditions




No reservoir



Reservoir Full

Test Grouting/Production Grouting Program

- Results of test grouting program
 - Spring flows not modified significantly – test section too short
 - Grout takes indicated production grouting costs acceptable if test section representative of remainder of grouting area



Performance

- Production grouting completed
 - Cost higher than estimated
- Reservoir holds water



Thank You

Questions?